

Legend

- Kirkwood-Cohansey Aquifer Monitoring Well
- Composite Confining Bed Monitoring Well
- Vincentown Aquifer Monitoring Well
- Missing Monitoring Well
- Groundwater Contour Line
- Groundwater Contour Line Inferred


Note

MW-42 could not be located during the 2009-2010 monitoring well development and sampling events. Multiple attempts were made using a magnetometer and gps equipment to locate the well. Well is believed to be buried under a debris pile.



Weston Solutions, Inc.

205 Campus Drive Edison, New Jersey 08837-3939
TEL: (732) 417-5800 Fax: (732) 417-5801
http://www.westonsolutions.com



REPORT DATE:

MARCH 2011

DRAWING:

09035_FMP_GW_Contours_Kirk-Cohan.mxd
PATH: L:/SHERWIN/GIS/MXD/
2011_03_FMP_Site_Eval/

REVISION No.

0

WORK ORDER No.

20076.022.079.0005

PROJECT MANAGER:

S. Jones

CHECKED BY:

A. Fischer

CONTRACT No.

DELIVERY ORDER No.

DRAWN/MODIFIED BY:

A. SALAZAR

DATE CREATED:
02/24/2011

CLIENT NAME:

The Sherwin-Williams Company

PROJECT NAME:

Former Manufacturing Plant
Remedial Investigation

DRAWING TITLE:

FORMER MANUFACTURING PLANT
GROUNDWATER CONTOUR MAP
KIRKWOOD-COHANSEY WELLS
(AUGUST 2, 2010)

FIGURE:

37

SCALE:

1" = 100'

DATE:

MARCH 2011